



Underwriters Laboratories Inc.

1655 Scott Boulevard
Santa Clara, California 95050-4169
United States Country Code (1)
(408) 985-2400
FAX No. (408) 295-3256
<http://www.ul.com>

SA5723

December 18, 2002

Pacific Seismic Products Inc.
Lancaster, CA

Fax No: 1-661-942-0999

Attention: Mr. Bill Keller

Reference: UL File SA5723 Earthquake Actuated Shutoff Systems
(FFPH)

Subject: Seismic Actuated Electrical Switch Assembly,
Model 510

Dear Mr. Keller:

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

UL's investigation of your product has been completed at no charge to your company and the product was determined to comply with the applicable requirements of the Standard for Earthquake Actuated Automatic Gs Shutoff Devices, ASCE 25-97.

This fax temporarily supplements the UL Follow-Up Services Inspection Procedure and serves as authorization to apply the UL Listing Mark only at the factory under UL's Follow-Up Service Program to the above product, which is constructed as described below:

Identical to products covered in the UL Follow-Up Services Inspection Procedure, File SA5723, Volume 1, Section 3.

This authorization applies only to the address on this letter.

This authorization is effective for 90 days from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that the Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

A not-for-profit organization
dedicated to public safety and
committed to quality service

Received 12-18-2002 03:42am

From-4082963256

To-KOSO/PSP

Page 002

SA5723
December 18, 2002
Page 2

Products which bear the UL Mark shall be identical to those which were evaluated by UL and found to comply with UL's requirements.

If changes in construction are discovered, authorization to use the UL Mark may be withdrawn and products that bear the UL Mark may have to be revised (in the field or at the manufacturer's facility) to bring them into compliance with UL's requirements.

Regards,

Reviewed by:

Greg Okada
Staff Engineer
Conformity Assessment Services
Section 3015W

Lester Wong
Associate Project Engineer
Conformity Assessment Services
Section 3015W

Telephone: 408-876-2444
Email: Gregory.L.Okada@us.ul.com

Telephone: 408-876-2202
Email: lester.wong@us.ul.com